







WOOD SERVING TABLE

REVIEWED BY THE PARK STANDARDS COMMITTEE, AND APPROVED BY THE CHIEF OF DESIGN & CONSTRUCTION

2 Ging

11/08/2022

507 SHEET 2 OF 3 NOT TO SCALE

STD PLAN

EAST BAY REGIONAL PARK DISTRICT - STANDARD PLANS

## ADA ACCESSIBILITY

- THE CLEAR GROUND SPACE AND ACCESSIBLE SEATING AREA DIMENSIONS SHOWN ON SHEET 1 ARE THE MINIMUMS REQUIRED AT ADA ACCESSIBLE TABLE LOCATIONS AND RECOMMENDED FOR ALL OTHER TABLE LOCATIONS.
- 2. ACCESSIBLE SEATING AREA MAY BE LOCATED AT ONE OR BOTH ENDS OF THE TABLE.
- 3. THE CLEAR GROUND SPACE AND ACCESSIBLE APPROACH SHALL NOT OVERLAP PATHS OF TRAVEL, OUTDOOR RECREATION ROUTES, TRAILS, OR ANY OTHER REQUIRED CLEAR GROUND SPACE.
- 4. THE CLEAR GROUND SPACE, ACCESSIBLE SEATING AREA, AND ACCESSIBLE APPROACH SHALL BE FIRM AND STABLE. RECOMMENDED AC OR CONCRETE PAVED SURFACES SHALL SLOPE A MAXIMUM OF 2% MEASURED IN ANY DIRECTION. WHERE THE SURFACE IS NOT PAVED, THE SLOPE MAY BE INCREASED TO A MAXIMUM OF 5% ONLY AS REQUIRED TO PROVIDE ADEQUATE DRAINAGE.
- 5. IF THERE ARE TWO OR MORE PICNIC TABLES, AT LEAST 20%, BUT NEVER LESS THAN TWO, SHALL BE ACCESSIBLE TABLES.

## **MATERIALS**

- 6. WOOD PLANKS SHALL BE 3X12, S4S EE  $(2\frac{1}{2})$ " X  $11\frac{1}{4}$ " DIMENSIONS WITH EASED EDGES).
- 7. WOOD PLANKS SHALL BE SEASONED DRY WITH A MAXIMUM MOISTURE CONTENT OF 19%, WESTERN RED CEDAR NO. 2 CLEAR OR BETTER, OR FSC CERTIFIED REDWOOD CONSTRUCTION HEART OR BETTER.
- 8. FASTENERS SHALL BE HOT-DIP GALVANIZED PER ASTM A153.
- 9. CONCRETE SHALL BE COMMERCIAL 5-SACK PRE-MIX CONCRETE OR EQUIVALENT.
- 10. SEE STANDARD PLAN 504F FOR FABRICATION OF STEEL BRACES.
- 11. WOOD PLANKS, FASTENERS AND TABLE BRACES, MAY BE AVAILABLE AT PARK DISTRICT CENTRAL STORES, FOR PURCHASE BY PARK DISTRICT STAFF ONLY.

## **WORKMANSHIP**

- 12. LOCATE UNDERGROUND UTILITIES PRIOR TO DIGGING. CALL USA (UNDERGROUND SERVICE ALERT) 1-800-277-2600, MON THRU FRI 6AM TO 7PM, A MINIMUM 2 WORKING DAYS WITH A MAXIMUM 14 CALENDAR DAYS, TO OBTAIN A TICKET. CONTACT THE DISTRICT INSPECTOR OR PARK SUPERVISOR FOR DISTRICT UTILITIES NOT LOCATED BY USA.
- 13. WOOD PLANKS SHALL NOT BE COATED (DO NOT SEAL, PAINT, OR STAIN).
- 14. ENDS OF WOOD PLANKS SHALL BE EASED  $\frac{1}{4}$ "R ALL AROUND.
- 15. PROJECTING BOLT ENDS SHALL BE CUT FLUSH WITH PLANKS AFTER TIGHTENING. ANY SHARP EDGES OR SHARP POINTS SHALL BE MADE DULL.
- 16. INSTALL WASHERS UNDER NUTS AND BOLT HEADS IN CONTACT WITH STEEL MEMBERS.
- TABLE BRACES SHALL BE INSTALLED PLUMB AT CENTER OF CONCRETE FOOTING.
- 18. ANY DAMAGE TO PAINTED METAL FINISH SHALL BE TOUCHED-UP WITH PRIMER AND PAINT PER DISTRICT STANDARD PLAN 003, PAINTING AND STAINING SPECIFICATION.



WOOD SERVING TABLE

REVIEWED BY THE PARK STANDARDS COMMITTEE, AND APPROVED BY THE CHIEF OF DESIGN & CONSTRUCTION

L Gaign

11/08/2022

507 SHEET 3 OF 3 NOT TO SCALE

STD PLAN

EAST BAY REGIONAL PARK DISTRICT - STANDARD PLANS